


**Photos of Existing Conditions**



Looking downstream from near undercut tree



Looking upstream at cut bank and undercut cottonwood tree



Looking upstream at severe bank undercut at tree. Upstream end of legacy riprap visible in foreground.



Legacy riprap to be vegetated.



**Flood conditions on May 10, 2017. Flow is left to right, bank erosion and development of scour hole at cottonwood tree is evident.**