

**Additional Information**

(10) (f) The Groundwater table level has not been an issue. During periods of high water in the 80's and early 90's the Mizer Ditch just north of the property would overflow due to lack of maintenance, and direct water to our property, resulting in high ground water. The head gate was rebuilt after the last event and the ditch ceased to be an issue.

(90's)

